Appendix 2:
Northern Gatehouse—Howard Town Mill



Northern Gatehouse from Victoria Street



Northern Gatehouse (rear elevation)



Gatehouses in context from Victoria Street



Northern Gatehouse context with mill to rear



Illustrating poor condition of remaining floor structure and extensive contamination from pigeon droppings



Note deterioration of stone supporting structure and poorly executed repairs to support

Northern Gatehouse—Howard Town Mill



Internal elevation of heavily altered rear wall



Illustrating lack of internal finishes



Roof—to remain unaltered during works