DESIGN AND ACCESS STATEMENT

96 Green Lane, Buxton

Replacement windows

Existing timber windows are becoming rotted and keep swelling and cracking double glazing units. New more efficient upvc requested

New conservatory

Required in matching upvc on front as there is no sun at rear