HPK/2012/0258

BATH HOUSE, 2 MACCLESFIELD ROAD, BUXTON SK17 9AH (Grade II Listed Building)

Schedule of Windows that may require restoration work

15 MAY 2012

LOCATION	LETTER	NO. OF WINDOWS	TYPE OF WINDOW
SECOND FLOOR	a	2	Yorkshire sash, 6 pane windows.
	b	1	4 pane sash window.
	c	1	4 pane sash window.
FIRST FLOOR	d	1	9 pane sash window.
	e	1	4 pane sash window.
	f	1	Bay with sash window. Lead roof will need replacement or repair.
	g	1	9 pane sash window.
	h	1	6 pane side hung casement window.
	c	1	4 pane sash window.
GROUND FLOOR	e	1	4 pane sash window.
	f	1	1 bay with sash window.
	c	1	4 pane sash window.
	d	1	9 pane sash window.
	i	1	2 pane side hung opening light window.
	j	1	4 pane sash window.
	k	1	Small top hung opening light and fixed bottom light window.
	L	1	2 pane side hung opening light window.

25th April, 2012

Andrew Humphries RIBA
Chartered Architect