

TOTAL PAVEMENT THICKNESS

- Sanderson Associates (Consulting Engineers) Ltd. ("the consultant"), has not checked or verified, and shall have no liability whatsoever for any inaccuracies which may be attributable to any data, reports, base plan(s) and drawings provided by the client, or purchased by the consultant on the basis that such materials may have been prepared by a third party.
- The consultant shall not be liable for the use by any person of any document for any purpose other than that for which the same were provided by the consultant.
- No liability whatsoever is accepted by the consultant for any error or omissions.
- The consultant accepts no liability for any vehicle specification errors within the vehicle track software used and / or its version.
- The locations of utilities apparatus, if shown, is reproduced from plans supplied to the consultant, although care has been taken when duplicating this information. These locations are approximate only and no guarantee can be given for their accuracy. It is the client's or its appointed professional responsibility to ensure that the correct location on site by hand dug trial holes or other appropriate means prior to mechanical excavation.
- Service connections are not shown but their presence should be anticipated.
- Reference to any third party equipment shown on this drawing was only relevant at the time the drawing was prepared.
- It is the client's responsibility to ensure that any equipment ordered meets the design.

Rev	Amendment	Drawn	Date	Checked
-----	-----------	-------	------	---------

PRELIMINARY
DRAWING

Client

HJK Construction

Project Title

Hallsteads, Dove Holes

Drawing Title

Construction Details

Scale AS SHOWN

Drawn By TOD

Drawing Size A1

Checked By PJM

Date _____

November 2023

Approved By

PJM

Drawing Number
301174-0703

Rev