


TENDER ISSUE NOT FOR CONSTRUCTION



New 12 thk plate bolted to underside of RSAs

New 12 thk plate bolted to underside of RSAs

New 12 thk plate bolted to underside of RSAs

150x90x12 RSA

N 2 5

New 150x90x12 RSA

New 2/ 80x80x10 RSAs + 450x6 thk plate

New 150x90x12 RSA

New 150x90x12 RSA

New 12 thk plate bolted to underside of RSAs

New 12 thk plate bolted to underside of RSAs

DETAIL ELEVATION; F

THE OCTAGON

RING BEAM REPAIRS ELEVATION F **PAVILION GARDENS**

		FOR INFORMATION NOT FOR CONSTRUCTION	MATION RUCTION
	Drawn nw		Eng sw
	Scales	Scales As noted at A1	
	Drawing No		Ver



23765/13

4



Consulting Engineers
1 Kayes Walk, Nottingham NG1 1PY
Tel: 0115 950 7977 Fax: 0115 950 0302
E-mail: notts@pricemyers.com www.pricemyers.com