

Front elevation to garage, Door moved over to give access becauce of extension. Timber lintel reused. Note stones A and B as original and line through Building height increased by approx 300mm to take new roof deck and slates (stone work not increased).



Right side of garage entrance also showing door to store



Rear End. Wing walls made good with new infill of timber horizontal rough cut boards Height of rear elevation as existing.





Stones A, B and D and window opening and cill E and G remain unchanges as does most of this elevation. C can be clearly identified as a stone reused as many others. Crack has just been filled. Window H has been moved to where the stone was not good.

The Foot Print of the building remains unchanged.



Elevation as existing



Wall as existing showing existing window The remainder of this wall was behind shrubbery.



With the removal of shrubbery this wall required considerable making good and repointing, the rear end being rebuilt



Existing link wall from garage side showing existing window

NOTES:

Randfield Associates take no responsibility for any dimensions obtained by scaling from this drawing. If no dimension is shown the recipient must ascertain the dimension specifically from the Architect or by site measurement. Supplying this drawing in digital form is solely for convenience and no reliance may be placed on digital data. All data must be checked against hard copy. Dimensions must be checked on site. Any discrepancies must be reported to the Architect immediately. This drawing is copyright of Randfield Associates.

REV:	DESCRIPTION:	DATE:
:	:	:
:	:	:
:	:	:
:	:	:
:	:	:
:	:	:

-1000 -500 0 1000 2000 3000

Scale 1:50 A2

RANDFIELD *associates*
Saunders : King : Moran
CHARTERED ARCHITECTS
Forge Bank Studio
1a Longhurst Lane Marple Bridge Stockport SK6 5AE
Tel: 0161 427 8485 Fax: 0161 427 5770
e-mail: info@randfieldassociates.co.uk
web: www.randfieldassociates.co.uk
Planning & Design Consultants : Interior Design : Building Inspections & Surveys : Historic & Listed Building Specialists

Client:	Mr and Mrs G A Hardy		
Job:	Refurbish Garage		
Drawing:	PHOTO CONPARISON		
Scale: 1:50	Date: Dec 2011	Drawn: ld	
Job No: 2932	Dwg No: 25	Rev: -	