


Appendix E

CCTV Drainage Survey



DATA NOTES
DRAWING IS BASED ON SITE DATA, DATA PROVIDED BY
PINNACLE TO LASER SURVEYS LIMITED.
LEVELS ARE RELATED TO — SUPPLIED ORIGIN DATA.

[illegible]

CTVW Relative to Traffic Number in CTVW Report


NOTES

- * Two species (shown above) should be treated with caution and species identification is advised.
- Although this is a digital survey the accuracy and amount of detail shown is only commensurate with the graphical means of mapping an aquifer. Care should be exercised when working in larger areas.
- Within tolerance is the ability of the boundaries on shown above, may represent the extent of highly permeable materials.
- Water entry effort has been made to ensure accuracy on this plan. Additional effort has been made to ensure that the boundaries shown are accurate and consistent.
- Each level has been taken in the bottom of the channel.

UNDERGROUND SERVICES

- 1) Although every effort has been made to trace underground services using radioteletest no guarantee can be given that all have been found. Due to their nature, conductive carrier types of gas and water pipes have not been possible to trace.
- 2) This survey has been carried out in accordance with the RCE specification for tracing underground utilities at scales of 1:500 and larger.
- 3) In the absence of evidence to the contrary the routes of confirmed manhole connections are assumed to be direct and straight.
- 4) Small gully's and downpipes that go straight into the ground could not be traced due to restrictive access.

SHEET LAYOUT



BUXTON WATER PLANT
STATION ROAD
BUXTON
SK17 6AQ
CCTV SURVEY

SURVEYED FOR	Pinnacle Mercury House Brookwater Way Walsby Garden City Hertfordshire	SURVEYOR	M Peasmore - Truse P Jiles - CCTV
		DATE	May 2011

NO	DATE	REVISION


DRAWING NO	T 6862/1	REV	0
------------	----------	-----	---

DRAWING TITLE	CCTV
SCALE	1 : 200 (AO)

SEE ALSO DWG NOS	
------------------	--

SHEET	1 of 2
REF NO	T 6862

REF NO	1 5502



DISCLAIMER:
OPINING IS BASED ON SITE DATA. DATA PROVIDED
FORWARD TO USER SURVEYS LIMITED.
LEVELS ARE INDICATED TO 1/4" SURVEYING DATA.

[illegible]

CEP Year	Relation to Earlier Number in CEP Year
1990	1990
1991	1991
1992	1992
1993	1993
1994	1994
1995	1995
1996	1996
1997	1997
1998	1998
1999	1999
2000	2000
2001	2001
2002	2002
2003	2003
2004	2004
2005	2005
2006	2006
2007	2007
2008	2008
2009	2009
2010	2010
2011	2011
2012	2012
2013	2013
2014	2014
2015	2015
2016	2016
2017	2017
2018	2018
2019	2019
2020	2020
2021	2021
2022	2022
2023	2023
2024	2024
2025	2025
2026	2026
2027	2027
2028	2028
2029	2029
2030	2030
2031	2031
2032	2032
2033	2033
2034	2034
2035	2035
2036	2036
2037	2037
2038	2038
2039	2039
2040	2040
2041	2041
2042	2042
2043	2043
2044	2044
2045	2045
2046	2046
2047	2047
2048	2048
2049	2049
2050	2050
2051	2051
2052	2052
2053	2053
2054	2054
2055	2055
2056	2056
2057	2057
2058	2058
2059	2059
2060	2060
2061	2061
2062	2062
2063	2063
2064	2064
2065	2065
2066	2066
2067	2067
2068	2068
2069	2069
2070	2070
2071	2071
2072	2072
2073	2073
2074	2074
2075	2075
2076	2076
2077	2077
2078	2078
2079	2079
2080	2080
2081	2081
2082	2082
2083	2083
2084	2084
2085	2085
2086	2086
2087	2087
2088	2088
2089	2089
2090	2090
2091	2091
2092	2092
2093	2093
2094	2094
2095	2095
2096	2096
2097	2097
2098	2098
2099	2099
2100	2100
2101	2101
2102	2102
2103	2103
2104	2104
2105	2105
2106	2106
2107	2107
2108	2108
2109	2109
2110	2110
2111	2111
2112	2112
2113	2113
2114	2114
2115	2115
2116	2116
2117	2117
2118	2118
2119	2119
2120	2120
2121	2121
2122	2122
2123	2123
2124	2124
2125	2125
2126	2126
2127	2127
2128	2128
2129	2129
2130	2130
2131	2131
2132	2132
2133	2133
2134	2134
2135	2135
2136	2136
2137	2137
2138	2138
2139	2139


NOTES

- * Tree species [where shown] should be treated with caution and identification is advised.
- * Although this is a digital survey the accuracy and amount of data shown is only approximate with the graphical needs of mapping as specified. Care should be exercised when making to larger scale maps.
- * Values between in the vicinity of the boundaries on these plots, represent the effect of locally scattered canopy.
- * Whilst every effort has been made to achieve accuracy in the photo-interpretation, levels and forest levels should be checked against ground conditions.
- * Back to back trees from adjacent plots should be shown.

UNDERGROUND SERVICES

- 1) Although every effort has been made to trace underground services using radio-detection no guarantee can be given that all have been found. Due to their complexity, certain types of gas and water pipes have not been possible to trace. Service hole holes may be the only way to determine the exact location.
- 2) This survey has been carried out in accordance with the RICS specification for tracing underground utilities at scales of 1:500 and larger.
- 3) In the absence of evidence to the contrary the routes of confirmed manhole connections are assumed to be direct and straight.
- 4) Small gully's and downpipes that go straight into the ground could not be traced due to restrictive access.

SHEET LAYOUT



BUXTON WATER PLANT
STATION ROAD
BUXTON
SK17 6AQ
CCTV SURVEY

SURVEYED FOR	Private Narcy House Broadwater Way Steyn Garden City Northampton AL7 3RD	SURVEYOR	M Peasmore - Tree P Jinks - OCTV
		DATE	May 2011

NO	DATE	REVISION		
DRAWING NO		T 6862/2	REV	
DRAWING TITLE		CCTV		
SCALE		1 : 200 (A0)		
SEE ALSO DWG NOS				
SHEET		2 of 2		
REF NO		T 6862		