SECTION 9 - ADDITIONAL INFORMATION

PHOTO 1 HPK/2011/1513

NEW FRONT DOOR, TAKEN 17/09/11
THE WATER STAIN ON THE LEFT
WAS PRESENT IN THE BOARD
BEFORE CONSTRUCTION OF THE DOOR

PHOTO 2

IMAGE FROM GOOGLE MAPS C.2008
SHOWING THE OLD FRONT DOOR.
IT ALSO SHOWS THE DETERIORATION
OF THE STONEWORK IN THE BOTTOM
COURSES

PHOTOS 3, 4 & 5

IMAGES SHOWING A RECENT WINDOW
SET MADE BY DOMINIC NAYLOR
TO ILLUSTRATE THE WAY THIS IS
MATCHED TO EXISTING STONEWORK
AND TO SHOW THE TYPE OF TOOLING
THAT WILL BE USED TO GIVE
AN APPROPRIATE

HIGH PEAK BOROUGH COUNCIL
RECEIVED
29 SEP 2011
FILE REF






Web Images Videos Maps News Shopping Gmail more
Google maps
UK
Hadfield Road, Glossop, Derbyshire, United Kingdom
Address is approximate
« Photos

