






PHOTOGRAPHIC RECORD BEFORE EXTENSION WORKS
SHOWING EXISTING WALL ADJACENT TO THE GARAGE
(GARAGE WAS DEMOLISHED UNDER PREVIOUS APPROVAL)







PHOTOGRAPHIC RECORD OF WORKS BEING UNDERTAKEN TO REINSTATE THE COLLAPSED BOUNDARY LINE







PHOTOS SHOW RETAINING STRUCTURE IN PLACE PRIOR TO REINSTATEMENT OF LIMESTONE BOUNDARY
THE LINE OF WHICH IS INDICATED BY THE CONCRETE PLINTH BASE (ROUGH LINE OF EXISTING COLLAPSED WALL)

39-41 MACCLESFIELD OLD ROAD

DWG: RIVERBANK BOUNDARY
39-41 MACCLESFIELD OLD ROAD
BUXTON

REVISIONS:

NTS	CHECKED:
DATE: JULY 12	DRAWN:

©THIS DRAWING AND THE BUILDING WORKS DEPICTED ARE THE COPYRIGHT OF AJS ARCHITECTURE AND MAY NOT BE REPRODUCED OR AMENDED EXCEPT BY WRITTEN PERMISSION. NO LIABILITY WILL BE ACCEPTED FOR AMENDMENTS MADE BY OTHER PERSONS. - DO NOT SCALE OFF DRAWING. CONFIRM ALL DIMS ON SITE

A.J.S ARCHITECTURE
32 carr road.
buxton.
derbyshire.
sk17 6wf.
h: 01298 26062
m: 07794 400237



PHOTOS 01

39-41 MACC OLD