Appendix 1 –
Site photographs



Photo 1 – View looking North West along Burnside Avenue. The site is to the left of the photograph.



Photo 2 – view of site looking South West along Burnside Avenue.



Photo 3 - view of site looking South West along Burnside Avenue from road bridge over culvert.



Photo 4 – manhole covers on Burnside Avenue (access to culvert).



Photo 5 – view of Black Brook entering box culvert beneath Burnside Avenue.



Photo 6 - view of Black Brook entering box culvert beneath Burnside Avenue.



Photo 7 – view of housing estate adjacent to site.



Photo 8 – view of the site looking North West.



Photo 9 – view of Black Brook.



Photo 10 – view of Black Brook.



Photo 11 – view of Black Brook.



Photo 12 – view of Warm Brook to the South of the site boundary.



Photo 13 – view of Warm Brook to the South of the site boundary.



Photo 14 – view of road bridge.



Photo 15 – view beneath road bridge with foot bridge visible.



Photo 16 – view beneath footbridge.



Photo 17 – view of site looking east.



Photo 18 – view of main road.



Photo 19 – view of woodland to the South West of Black Brook.



Photo 20 – view of woodland to the South West of Black Brook.



Photo 21 – view of industrial site to the South West.



Photo 22 – view of the road bridge looking from the main road.



Photo 22 – view of site looking South East.



Photo 23 – view of telegraph pole on site.



Photo 23 – test hole.



Photo 24 – river cutting.



Photo 25 – view of houses opposite site.