




KEY

- Retention Category A:** Trees whose retention is most desirable. Vigorous healthy tree of good form, free from obvious faults and of significant amenity value.
- Retention Category B:** Trees whose retention is desirable. Trees which are in a moderate to good condition although some minor faults may require correction by surgery.
- Retention Category C:** Trees whose condition is moderate to poor and usually require a significant amount of tree surgery or be located in an area not readily accessible to the public.
- Retention Category U:** Trees & shrubs which are dead, dying or dangerous. Trees which are so damaged and diseased as to be incapable of further satisfactory development. Trees in this category should be removed.
- Off-site tree**

The survey methodology is adopted from that contained in BS 5837:2012 'Guides to Trees in Relation to Construction'. The trees are assigned retention categories on the basis of their general form, health, and amenity value.

NB To be read in conjunction with A4 Tree Survey Report



Rev	Description	Initial	Date

Saville Landscape Design Ltd
 Hatherlow House
 Romiley
 Stockport
 Cheshire
 SK9 3DY

Telephone : 0161 406 7333
 E-mail : info@savillandscape.co.uk
 Web : www.savillandscape.co.uk

saville
LANDSCAPE DESIGN

Client	TADW Architects
Project Title	Buxton Rd, Bridgemont
Drawing Title	Tree Survey
Status	INFORMATION

Scale @ A1	1:200	Drawn By	KAS	Checked By		Authorised By	
	Date	Date	Date	Date	Date	Date	Date
Project No.	057	Drawing No.	01	Revision			