

CERTIFICATE OF ASBESTOS ANALYSIS

NS Ref. : J007643
Date Received : 21/07/2017
Samples Analysed By : Jon Feightman
Date Analysis Completed : 21/07/2017
Date Reported : 21/07/2017
Site Address : Wilshaw, Chinley, High Peak, SK23 6EJ
Samples Taken By : IST Risk Management
Client Ref (if required) : None Given

Client Sample Ref	Location	Description	Lab Ref	Asbestos Identification	Comments
1	Garage	Wall	BS007604	Chrysotile	

*N.A.D.I.S = No Asbestos Detected In Sample

The laboratory cannot be responsible for inaccurate or unrepresentative sampling. All sample descriptions and locations are provided by the client, the laboratory cannot be held responsible for inaccurate information

Analysis for asbestos in bulk materials using dispersion staining was carried out in accordance with our documented in-house method NSTM4 which is based on the methodology set out in HSG 248

For and on behalf of
North Star Environmental Ltd



Jon Feightman
Lab Tech