

Client: Concertus Design & Property
Consultants Limited

Date: 06.10.2021

Project: C3678

Site: Former Glossopdale College

Photo No: 03

Comments: Mature trees and
demolition rubble in the east of the
site.



Client: Concertus Design & Property
Consultants Limited


Date: 06.10.2021

Project: C3678

Site: Former Glossopdale College

Photo No: 04

Comments: Scrubland and slope in the south of the site with mature trees along the southern boundary.



Client: Concertus Design & Property
Consultants Limited

Date: 06.10.2021

Project: C3678

Site: Former Glossopdale College

Photo No: 05

Comments: Photo taken from the northern boundary looking west over a former car park.



Client: Concertus Design & Property
Consultants Limited

Date: 06.10.2021

Project: C3678

Site: Former Glossopdale College

Photo No: 06

Comments: Photo taken from the
centre of the site looking south

