

Notes :

This drawing has been prepared in accordance with BS 5837:2012.

This drawing is intended to be printed and used in colour only, and for no purpose other than the consideration of trees in accordance with BS 5837.

BS5837:2012 Cascade chart for tree quality assessment			
Category & Definition	Criteria (including subcategories where appropriate)		Identification on plan
Trees unsuitable for retention			
Category U	Trees that have a serious, irreparable structural defect, such that their early loss is expected due to their poor structural condition. These trees are not suitable for retention.		Red on plan RGB 127,0,0
Trees to be considered for retention			
Category A	1. Rarely horticultural qualities	2. Rarely landscape qualities 3. Rarely cultural values, including conservation	Light Green RGB 9,255,0
Category B	Trees that are particularly good examples of their species, and are of high quality.	Trees that are particularly good examples of their species, and are of high quality.	Mid blue RGB 64,255,0
Category C	Trees of low quality with an estimated remaining life expectancy of at least 10 years.	Trees with minimal conservation or cultural value	Grey RGB 99,191,191

- KEY
- Root Protection Area (RPA)
 - Tree Stem
 - T1 Tree No.
 - Tree Protection Fencing
 - Storage Area
 - Contractor Parking
 - Ground Protection
 - 'No-Dig' Parking area

Rev	Details	Date	Checked By
Drawing Number AEL-18856-TPP			
Apex Environmental Ltd 3 Lawrence Way, Lichfield, WS13 6RD TEL. 0121 249 1235 e-mail. info@ael-treeconsultants.co.uk web: www.ael-treeconsultants.co.uk			
Client Mr D Rai			
Project Portland Care Home, Buxton			
Title Tree Protection Plan			
Scale	Date	Drawn By	Checked By
1:200	09/11/2023	RJH	A
THIS DRAWING IS CONFIDENTIAL AND MUST NOT BE REPRODUCED WITHOUT THE CONSENT OF APEX ENVIRONMENTAL LTD			

