

Dove Holes Business Unit

8-10 Hallsteads

Existing Site Photographs



001 – Vehicular Access road off A6

Dove Holes Business Unit

8-10 Hallsteads
Existing Site Photographs



002 – Asbestos Block to be removed and replaced with Enclosed Skips. Area to Right hand side to be screened with plants, etc.



003 – Existing Main Entrance Doors

Dove Holes Business Unit

8-10 Hallsteads

Existing Site Photographs



004 - Disabled access ramp to rear of property. DDA/ DOC M compliant handrails to be installed.



005 – Proposed tarmac area, with car parking bays as per proposed plan.

Dove Holes Business Unit

8-10 Hallsteads

Existing Site Photographs



006 – View to car parking space/ rear of proposed skip location.



007 – Proposed Car parking Area.

Dove Holes Business Unit

8-10 Hallsteads

Existing Site Photographs



008 – Door access to front of property



009 – Hardstanding to front of property / View of A6 Hallsteads.